

TEST REPORT

Report No.:HC80124A/2020Page:1of7Date:September 4, 2020

STEALTH 1 - 7550 HIGHWAY 27, WOODBRIDGE, ONTARIO, L4H 0S2, CANADA

The following merchandise was submitted and identified by the vendor as:		
Product Description:	High-Performance Fanless System	
Style/ Item No .:	LPC-96X/ No.1	
Quantity:	Total 1 piece	
Testing Period:	Aug 22, 2020 to Sep 1, 2020	
Note:	(Client's declaration)The Style LPC-96X and SR-296X are the same product;	
	The difference in style name is only based on different market.	

We have tested the submitted sample(s) as requested and the following results were obtained: <u>Test Required:</u> (According to client's test specification, please see following sheets in detail.)

- 1. Random Vibration Test
- 2. Mechanical Shock Test

Test Results : -PLEASE SEE ATTACHED SHEETS-

*HC80124/2020, dated on September 1, 2020, is hereby canceled and replaced by HC80124A/2020.

Signed for and on behalf of SGS TAIWAN Ltd.

Allen Wang Asst. Supervisor

Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 90 days only. This test report cannot be reproduced, except in full, without prior written permission of the Company. 除非另有說明,此報告結果僅對測試之樣品負責,同時此樣品僅保留 90 天。本報告未經本公司書面許可,不可部份複製。 This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at <u>www.sqs.com.tw/Terms-and-Conditions</u> and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at <u>www.sqs.com/en/terms-and-conditions</u> and, for electronic format issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

 Reliability Laboratory/ No.31, Wu Chyuan Road, New Taipei Industrial Park, Wuku District, New Taipei City, Taiwan

 可靠度實驗室/新北市五股區新北產業園區五權路 31 號

 t (886-2) 2299-3279

 f (886-2) 2299-9558

Member of SGS Group



TEST REPORT

Report No.:	HC8	80124A/	2020
Page:	2	of	7

1. Random Vibration Test:

Test Equipment:

Name	Brand	Model	Serial No.
Vibration Tester	King Design	EM-5000F2K-75N600	WR10923701
Controller	Crystal	spider	1001664
Control Accelerometer	WR	793-6	A4632
Vibration Test System	UNHOLTZ-DICKIE	SAI60-H560BAC/2/ST	474
Controller	Dactron	LASER	7110357
Control Accelerometer	PCB	353B34	LW213529

Lab Environmental Conditions:

Ambient temperature:	<u>(25 ± 3) °C</u>
Ambient humidity:	(55 ± 20) % RH

Test Location:

No. 31, Wu Chyuan Road, New Taipei Industrial Park, WuKu District, New Taipei City, Taiwan

Test Method/ Specification:

Test method:	IEC 60068-2-64, Edition 2.0: 2008				
Sample condition:	Operating (exec	Operating (execute "BurnIn Test")			
Wave form:	Random				
Frequency:	<u>(5 ~ 500) Hz</u>				
	Frequency (Hz)	Left Slope (dB/Oct.)	PSD (g ² /Hz)	Right Slope (dB/Oct.)	
	5	_	0.05	0	
	500	0	0.05		

 \Longrightarrow equivalent to 5.0 G_{rms}

Direction:

, T	
X, Y, Z axes (see	e photo 3 ~ 5)
20	

Duration: <u>30 minutes/ axis</u>

- Examine the appearance of specimen(s) by visual check and perform functional check after this test.
- Functional check: Turn on the power of specimen then examine the test program "BurnIn Test" could work normally or not.

Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 90 days only. This test report cannot be reproduced, except in full, without prior written permission of the Company. 除非另有說明,此報告結果僅對測試之樣品負責,同時此樣品僅保留 90 天。本報告未經本公司書面許可,不可部份復製。 This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at www.sqs.com.tw/Terms-and-Conditions and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at www.sqs.com/ent/erms-and-conditions/terms-and-conditions of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsfitication of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.



TEST REPORT

Report No.:	HC	80124A/	2020
Page:	3	of	7

Reliability Laboratory

Style/ Item No.:

LPC-96X/ No.1
Total 1 piece

Test Result:

Quantity:

Specimen:

Check Item Style/ Item No.	Appearance check (Visual check)	Functional check
LPC-96X/ No.1	No visible damage	Normal

Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 90 days only. This test report cannot be reproduced, except in full, without prior written permission of the Company. 除非另有說明,此報告結果僅對測試之樣品負責,同時此樣品僅保留 90 天。本報告未經本公司書面許可,不可部份復製。 This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at www.sgs.com.tw/Terms-and-Conditions and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at www.sgs.com/ent/erms-and-conditions/terms-e-document. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forger or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fulles extend to the law.

Reliability Laboratory/ No.31, Wu Chyuan Road, New Taipei Industrial Park, Wuku District, New Taipei City, Taiwan 可靠度實驗室/新北市五股區新北產業園區五權路 31 號 t (886-2) 2299-3279 f (886-2) 2299-9558



TEST REPORT

Report No.:	HC8	30124A/	2020
Page:	4	of	7

2. Mechanical Shock Test:

Test Equipment:

Name	Brand	Model	Serial No.
Shock Test System	LANSMONT	95-115D	M17656
Data Acquisition & Analysis System	LANSMONT	TP4 8A-CH SML 1115-001	1115-001
ICP Accelerometer	PCB	353M288	196437

Lab Environmental Conditions:

Ambient temperature:	(<u>25 ± 3) °C</u>
Ambient humidity:	(<u>55 ± 20) % RH</u>

Test Location:

No. 33, Wu Chyuan Road, New Taipei Industrial Park, WuKu District, New Taipei City, Taiwan

Test Method/ Specification:

Test Method:	IEC 60068-2-27, Edition 4.0: 2008
Sample condition:	Operating (execute "BurnIn Test")
Pulse shape:	<u>Half-sine</u>
Acceleration:	<u>50 g</u>
Pulse duration:	<u>11 ms</u>
Shock direction:	<u>6 faces ($\pm X$, $\pm Y$, $\pm Z$ axes, see photo 6 ~ 11)</u>
No. of shock:	3 shocks/ axis (total 18 shocks)

• Examine the appearance of specimen(s) by visual check and perform functional check after this test.

• Functional check: Turn on the power of specimen then examine the test program "BurnIn Test" could work normally or not.

Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 90 days only. This test report cannot be reproduced, except in full, without prior written permission of the Company. 除非另有說明,此報告結果僅對測試之樣品負責,同時此樣品僅保留 90 天。本報告未經本公司書面許可,不可部份復製。 This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at www.sqs.com.tw/Terms-and-Conditions and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at www.sqs.com/ent/erms-and-conditions/terms-and-conditions of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsfitication of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

Reliability Laboratory/ No.31, Wu Chyuan Road, New Taipei Industrial Park, Wuku District, New Taipei City, Taiwan 可靠度實驗室/新北市五股區新北產業園區五權路 31 號 t (886-2) 2299-3279 f (886-2) 2299-9558 www.tw.sgs.com Member of SGS Group



TEST REPORT

Report No.:	HC80124A/20		2020
Page:	5	of	7

Reliability Laboratory

Style/ Item No.:

LPC-96X/ No.1
Total 1 piece

Test Result:

Quantity:

Specimen:

Check Item Style/ Item No.	Appearance check (Visual check)	Functional check
LPC-96X/ No.1	No visible damage	Normal

Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 90 days only. This test report cannot be reproduced, except in full, without prior written permission of the Company. 除非另有說明,此報告結果僅對測試之樣品負責,同時此樣品僅保留 90 天。本報告未經本公司書面許可,不可部份復製。 This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at www.sgs.com.tw/Terms-and-Conditions and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at www.sgs.com/ent/erms-and-conditions/terms-e-document. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forger or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fulles extend to the law.


Reliability Laboratory/ No.31, Wu Chyuan Road, New Taipei Industrial Park, Wuku District, New Taipei City, Taiwan 可靠度實驗室/新北市五股區新北產業園區五權路 31 號 t (886-2) 2299-3279 f (886-2) 2299-9558



TEST REPORT

Report No.:	HC80124A/2020		
Page:	6	of	7

Test Photos:



Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 90 days only. This test report cannot be reproduced, except in full, without prior written permission of the Company. 除非另有說明,此報告結果僅對測試之樣品負責,同時此樣品僅保留 90 天。本報告未經本公司書面許可,不可部份復製。 This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at www.sgs.com.tw/Terms-and-Conditions and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at www.sgs.com/ent/erms-and-conditions/terms-e-document. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forger or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fulles extend to the law.


Reliability Laboratory/ No.31, Wu Chyuan Road, New Taipei Industrial Park, Wuku District, New Taipei City, Taiwan 可靠度實驗室/新北市五股區新北產業園區五權路 31 號 t (886-2) 2299-3279 f (886-2) 2299-9558



TEST REPORT

Report No.:	HC80124A/2		2020
Page:	7	of	7

Test Photos--Continued:



The End of Test Report

Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 90 days only. This test report cannot be reproduced, except in full, without prior written permission of the Company. 除非另有說明,此報告結果僅對測試之樣品負責,同時此樣品僅保留 90 天。本報告未經本公司書面許可,不可部份復製。 This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at www.sqs.com.tw/Terms-and-Conditions and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at www.sqs.com/ent/erms-and-conditions/terms-and-conditions of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsfitication of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.